## Weathertzation Assistance Program

## Work Order (Bid Form)

## **WORK ORDER INFORMATION**

Work Order Name: WO/12012NW2363/1

Work Order Type: Weatherization Audit Name: 12012NW2363

**CLIENT INFORMATION** 

Client Name: Address:

**Client ID:** 12012NW2363

Alt. Client ID:

**AGENCY INFORMATION** 

Agency: Northwest Tn. Economic Development Council Agency Phone: (731) 364-3228

**Address:** 231 South Wilson St. **Fax:** (731) 364-5029

Dresden, TN 38225-1312 Email Address:

Agency Contact: Woods, Max Work Phone: (731) 286-0332

Cell Phone: (731) 676-1414

Email Address:

Company Name & License Number:	
Contractor's Signature:	

## **COMMENT**

	Measure	1 Infilt	ration Redctn		Components					Inspected	
C	Comment	_			_						
		Foam ur	nder Kitchen Sink. May	need 2 or	3 cans						
		Door #1	Replace Snap-inWea Install Threshold and Caulk	•	Э						
		Door #2	Weahtherstrip Door shoe Caulk								
						Estimated			Actual		
#			Description / Comment	Units _	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
10	Miscellan Supplies	eous	Infiltration Reduction	Each	1						
(	Other Detail	ı						¬			
L											
					Measur	e Sub Total:		] ;	Sub Total:		
	Measure	2 DWF	l Pipe Insulation			Componer	nts			Inspected	
C	Comment					Estimated	4		Actual		
#	Material /	l abor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
	Insulation		DHW Pipe Insulation	Each	1						
2	Labor		DHW Pipe Insulation	Each	1						
(	Other Detail	ı									
					Measur	e Sub Total:		] ;	Sub Total:		
	Field Note	es:									

Client Name: Client ID: 12012NW2363 Alt. Client ID:

Measure 3 DV	/H Tank Insulation			Componen	its			Inspected
<b>Comment</b> Electric	С							
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Hot Water     Equipment	DHW Tank Insulation	Each	1					
2 Labor	DHW Tank Insulation	Each	1					
Other Detail								
			Measure	e Sub Total:		]	Sub Total:	
Comment Existin	frigerator Rplcmnt g refrig. Is in very bad sha eplace with a new energy		seal is		ompresor	is goin	g	Inspected
# #				Estimated			Actual	<b>-</b>
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Refrigerators	-	Each	1					
Other Detail								
			Measur	e Sub Total:		,	Sub Total:	
Field Notes:								

M	easure 5 Attic	Ins. R-30			Componen	<i>t</i> s A1			Inspecte
Col	<b>mment</b> Upgrade	Attic Access							
					Estimated			Actual	
# N	Waterial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 lı	nsulation	Attic Insulation - Cellulose, Blown - R-30	SqFt	672					
	Miscellaneous Supplies	Added Misc Cost	Each	1					
Oth	her Detail								
				Measur	e Sub Total:			Sub Total:	
F	Field Notes:								
F	Field Notes:								
F	Field Notes:								
М	easure 6 CO	Monitor is Needed			Componen	ts		,	Inspecte
Me		Monitor is Needed			<b>Componen</b> Estimated			Actual	Inspecte
Me Co	easure 6 CO	Monitor is Needed  Description / Comment	Units	Qty	-		Qty		Inspecte
<i>M</i> <sub>0</sub> <i>C</i> 0 # <i>N</i> 1 ⊢	easure 6 CO I		<i>Units</i> Each	<b>Qty</b> 1	Estimated		Qty	Actual	
Ma Con # M	easure 6 CO I mment Material / Labor Health and Safety	Description / Comment			Estimated		Qty	Actual	
Ma Co	easure 6 CO I mment Material / Labor Health and Safety tems	Description / Comment CO monitor	Each	1	Estimated		Qty	Actual	
McCol. # A. 1 H	Teasure 6 CO Instrument  Material / Labor  Health and Safety tems  Labor	Description / Comment CO monitor	Each	1	Estimated		Qty	Actual	
McCol. # A. 1 H	Teasure 6 CO Instrument  Material / Labor  Health and Safety tems  Labor	Description / Comment CO monitor	Each	1	Estimated		Qty	Actual	
McCol. # A. 1 H	Teasure 6 CO Instrument  Material / Labor  Health and Safety tems  Labor	Description / Comment CO monitor	Each Hour	1	Estimated			Actual	

_	mproper Venting (Clotl	nes Dryer	)	Componen	ts			Inspecte
Comment								
				Estimated	·		Actual	
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
1 Health and Safety Items	Equipment	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Measure O. Fin V	Minimo Ducklama (Attic)			<u> </u>	4-			Inspector
	Viring Problems (Attic) oper wiring connections			Componen				Inspected
				Componen  Estimated			Actual	Inspected
Comment (2) Impro				-		Qty		Inspected
Comment (2) Impro	oper wiring connections	J-box cov	ers	Estimated		Qty	Actual	
Comment (2) Impro  # Material / Labor  1 Health and Safety Items	oper wiring connections  Description / Comment	J-box cov	ers Qty	Estimated		Qty	Actual	
Comment (2) Impro  # Material / Labor  1 Health and Safety Items	Description / Comment Equipment	J-box cov <i>Units</i> Each	Qty	Estimated		Qty	Actual	
Comment (2) Impro  # Material / Labor  1 Health and Safety Items  2 Labor	Description / Comment Equipment	J-box cov <i>Units</i> Each	Qty	Estimated		Qty	Actual	
Comment (2) Impro  # Material / Labor  1 Health and Safety Items  2 Labor	Description / Comment Equipment	J-box cov <i>Units</i> Each	Qty	Estimated		Qty	Actual	
Comment (2) Impro  # Material / Labor  1 Health and Safety Items  2 Labor	Description / Comment Equipment	J-box cov  Units  Each  Hour	Qty 1	Estimated			Actual	
Comment (2) Impro  # Material / Labor  1 Health and Safety Items  2 Labor  Other Detail	Description / Comment Equipment	J-box cov  Units  Each  Hour	Qty 1	Estimated Unit Cost			Actual Unit Cost	
Comment (2) Impro  # Material / Labor  1 Health and Safety Items  2 Labor	Description / Comment Equipment	J-box cov  Units  Each  Hour	Qty 1	Estimated Unit Cost			Actual Unit Cost	

	Measure 9 Insta	all Bathroom Exhaust F	an		Componen	ts			Inspected
C	comment Replace	non-working bath exhau	ist and ver	nt thru	roof.				
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Bathroom exhaust fan	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	-	ace Un-Vent Heater irect vent heater and rem	nove un-ve		Componen eater. Gas a	and elect	rical are		Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Unspecified	Misc Material	Each	1					
	Other Detail								
	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:							_	

	Measure 11 Smo			Componen	Inspected				
C	omment								
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Smoke detector	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail						<b>-</b>		
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
			Work Or	der Gra	nd Total:		Gran	d Total:	